



Application Guide



IMPORTANT - Read Before You Begin Application:

- Store in safe dry place at 40-105F° (4 -41C°)
- Do not mix with other chemicals
- Seal container after use
- Keep out of reach of children
- Keep product from freezing
- To protect from overspray, cover any surrounding materials before application.

SkudoCURE™ is a Ready to Use product and should not be mixed or diluted with any other product. SkudoCURE™ should be applied at a rate of 1,000 to 1,500 sf per Gallon.

Application Steps



1. Apply to new concrete immediately after power trowel comes off the slab or once the bleed water has disappeared.

NOTE: Ensure that the finishers do not burn (over burnish) the slab that will create a cap. This will hinder penetration into the surface.



2. Apply product with low pressure pump sprayer and conical tip. Spray SkudoCURE™ to lightly wet the surface without creating puddles. Apply in a consistent, overlapping circular motion, holding the wand approximately 12 inches above the surface. SkudoCURE™ will absorb into concrete more quickly in some places than others. Do not over-apply. Do not allow product to puddle.



3. While spraying, immediately spread SkudoCURE™ evenly across the surface using a microfiber pad with SkudoCURE™ applied to the face.

4. Prevent overspray on other materials. If this happens, immediately rinse off any overspray with water.

5. Apply the SkudoCURE™ before any soft cutting operations.

6. Do not apply when ambient or surface temperature is below 40°F (4.4°C).

Cleaning

Tools in contact with SkudoCURE™ can be washed up with soap and water shortly after application.

Wet overspray on glass or metal can also be removed with soap and water. Use a solvent cleaner as soon as possible to remove any dried overspray.



For Professional use only.

Hazard statements: Causes severe skin burns and eye damage.

Precautionary statements: Do not actively breathe mist/vapors/spray. Ventilate enclosed application areas. Wash thoroughly after handling. Wear protective gloves/protective clothing/eye protection. If swallowed: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/doctor. Store locked up. Dispose of contents/container in accordance with local/regional/national/ international regulations.



Innovative, purpose-built surface protection systems. This is all we do.

www.skudousa.com 1-888-SKUDO-11 (1-888-758-3611)

V 1.0 11.2.21