



# Application Guide



## IMPORTANT - Read Before You Begin Application:

- Store in safe dry place at 40-105F° (4 -41C°)
- Do not mix with other chemicals
- Seal container after use
- Keep out of reach of children
- Keep product from freezing
- To protect from overspray, cover any surrounding materials before application.

SkudoCURE™ is a Ready to Use product and should not be mixed or diluted with any other product. SkudoCURE™ should be applied at a rate of 1,000 to 1,500 sf per Gallon.

### Application Steps



1. Apply to new concrete immediately after power trowel comes off the slab or once the bleed water has disappeared.

**NOTE:** Ensure that the finishers do not burn (over burnish) the slab that will create a cap. This will hinder penetration into the surface.



2. Apply product with low pressure pump sprayer and conical tip. Spray SkudoCURE™ to lightly wet the surface without creating puddles. Apply in a consistent, overlapping circular motion, holding the wand approximately 12 inches above the surface. SkudoCURE™ will absorb into concrete more quickly in some places than others. Do not over-apply. Do not allow product to puddle.



3. While spraying, immediately spread SkudoCURE™ evenly across the surface using a microfiber pad with SkudoCURE™ applied to the face.



4. Prevent overspray on other materials. If this happens, immediately rinse off any overspray with water.

5. Apply the SkudoCURE™ before any soft cutting operations.

6. Do not apply when ambient or surface temperature is below 40°F (4.4°C).

### Cleaning

Tools in contact with SkudoCURE™ can be washed up with soap and water shortly after application.

Wet overspray on glass or metal can also be removed with soap and water.

Use a solvent cleaner as soon as possible to remove any dried overspray.

### For Professional use only.

**Hazard statements:** Causes severe skin burns and eye damage.

**Precautionary statements:** Do not actively breathe mist/vapors/spray. Ventilate enclosed application areas. Wash thoroughly after handling. Wear protective gloves/protective clothing/eye protection. If swallowed: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/doctor. Store locked up.

Dispose of contents/container in accordance with local/regional/national/ international regulations.



Visit our website for more information

Innovative, purpose-built surface protection systems. This is all we do.

[www.skudousa.com](http://www.skudousa.com) 1-888-SKUDO-11 (1-888-758-3611)